

486

50X1-HUM

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL	-	U.S.	OFFICIALS	ONLY
SECURITY	INP	ORMATH	MC	

50X1-HUM

COUNTRY	Poland	REPORT	
SUBJECT	Progress and Plans at the Nowa Huta Project near Krakow	DATE DISTR.	30 October 1953
Ţ		NO. OF PAGES	<b>3</b>
DATE OF	INFO.	REQUIREMENT	50X1-HUM
PLACE AC	CQUIRED	REFERENCES	50X1-HUN
			30001-11010
	THE SOURCE EVALUATIONS IN THIS REP THE APPRAISAL OF CONTENT II (FOR KEY SEE REVERSI	TENTATIVE.	50X1-HUM
	OR A Mass 705% the nemerous was a second		
<i>(</i>	On 4 May 1953 the government made available Ministry of Heavy Industry the text of a seconding the putting into commission of the follows: "The agreement signed with the Selated that the Soviet Union would deliver the majority of the machines and installating giving a list of constructions which has built."	Nowa Huta foundry.  Oviet Union on 26 Jan  the complete do	by Bierut and con- The text ran as uary 1948 stipu- cumentation and
	corning the putting into commission of the follows: "The agreement signed with the Scalet that the Soviet Union would deliver the majority of the machines and installating giving a list of constructions which have built."	Nowa Huta foundry.  Die Union on 26 Jan  the complete do  Lons required. The  re been, or are in the	by Bierut and con- The text ran as uary 1948 stipu- cumentation and decree continues  50X1-HUMf being
	corning the putting into commission of the follows: The agreement signed with the slated that the Soviet Union would deliver the majority of the machines and installating by giving a list of constructions which have built.  The following parts of the various installs.	Nowa Huta foundry.  Die Union on 26 Jan  the complete do  Lons required. The  re been, or are in the	by Bierut and con- The text ran as uary 1948 stipu- cumentation and decree continues  50X1-HUMf being
	corning the putting into commission of the follows: "The agreement signed with the Sclated that the Soviet Union would deliver the majority of the machines and installatiby giving a list of constructions which have built."  The following parts of the various installs plans:	worst decree, signed  Nows Huta foundry.  District Union on 26 Jan  the complete do  lons required. The  re been, or are in th  utions have priority	by Bierut and con- The text ran as uary 1948 stipu- cumentation and decree continues  50X1-HUM being in construction
	corning the putting into commission of the follows: "The agreement signed with the Sclated that the Soviet Union would deliver the majority of the machines and installatiby giving a list of constructions which have built."  The following parts of the various installables:  a. Blast Furnaces:  (1.) Blast Furnace No. 1 with armory:	Nowa Huta foundry.  Discovery Union on 26 Jan  the complete do  Lons required. The  re been, or are in th  ations have priority  ng, ring main, hoist lation.  dling hall.  se No. 1 (three air-b.	by Bierut and con- The text ran as mary 1948 stipu- cumentation and decree continues  50X1-HUM  in construction  bridge, partial
	cerning the putting into commission of the corning the putting into commission of the follows: The agreement signed with the Solated that the Soviet Union would deliver the majority of the machines and installation by giving a list of constructions which have built.  The following parts of the various installables:  (1.) Blast Furnace No. 1 with armoristication liming, charging install (a.) Hearth building and iron is (b.) Block of heaters for Furnace armouring.)  (c.) Servicing building, chimney (2.) Blast Furnace No. 2 with armoristications.	Nowa Huta foundry.  Nowa Huta foundry.  Diet Union on 26 Jam the complete do  Lons required. The re been, or are in th  utions have priority  ng, ring main, hoist lation.  ddling hall.  No. 1 (three air-b r, hoist machinery but  ng and part of the res	by Bierut and con- The text ran as mary 1948 stipu- cumentation and decree continues  50X1-HUM being in construction  bridge, partial  last heaters with ilding.  maining construction.
	corning the putting into commission of the corning the putting into commission of the follows: The agreement signed with the Stated that the Soviet Union would deliver the majority of the machines and installative by giving a list of constructions which have built.  The following parts of the various installs plans:  (1.) Blast Furnace No. 1 with armoristicable lining, charging install (a.) Hearth building and iron 1s (b.) Block of heaters for Furnace armouring.)  (c.) Servicing building, chimney	Nova Huta foundry.  Nova Huta foundry.  Die Union on 26 Jam  the complete do  lons required. The  re been, or are in th  ations have priority  ng, ring main, hoist  lation.  dling hall.  e No. 1 (three air-b  , hoist machinery but  ng and part of the res  construction and but  (skip pit No. 1 is in	by Bierut and con- The text ran as mary 1948 stipu- cumentation and decree continues  50X1-HUM being in construction  bridge, partial  last heaters with ilding.  maining construction.  as finished state,

SECRET/CONTROL - U.S. OFFICIALS ONLY

STATE	x	ARMY	x	NAVY	x	AIR	X	FBI	AEC		ORR	Ev.	×	
										200	100			 
(Note: W	ashington	Distribution	Indic	ated By "X"	, Field	Distribution	Bu ii	##1						 

Ore Dressing Flant:  (1.) Preliminary crushing building.  (2.) Crushing building.  (3.) Sorting hall.  (4.) Ore, coke ash, and flue dust receiving bunkers.  (5.) Transporter galleries with transleading points with partial machine equipment.  (6.) Charge bunker building.  (7.) Half of the main ore dressing building (aglomerownia).  (8.) Chimmey, roads etc.  Power Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal wholoading bunkers.  (4.) Coal wholoading bunkers.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.   Sinch(Marghing. No.)  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m.  (24.) Tilting furnaces notes not clear whether open hearth or Bessemar - "piece precohylne").  (3.) Nos. 1, 2, 5 and foundations of, No. 4 carth works.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) Sleg and ladle preparation sections, flux (wlewki), briquette and dolomite stores.			7	1	1	
Ore Dressing Flant:  (1.) Preliminary crushing building. (2.) Crushing building. (3.) Sorting hall. (4.) Ors, coke sah, and flue dust receiving bunkers. (5.) Transporter galleries with transleading points with partial machine equipment. (6.) Charge bunker building. (7.) Half of the main ore dressing building (aglomerownia). (8.) Chimmey, roads etc.  (8.) Chimmey, roads etc.  (9.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (8.) Coal unloading bunkers. (9.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (8.) Coal unloading bunkers. (9.) Main switching and distribution plant. (8.) Main switching and distribution plant. (8.) Main transformer station 110/6 KV with electrical equipment.  Sideal working which  (1.) Part I of the main steelworks building - 545,000 cu. meters, length about 190 m.  (2.) Tilting furnaces not clear whether open hearth or Bessemer piece priscopylne notes not clear whether open hearth or Bessemer SOX1-HU  (1.) Part I of the main steelworks building - earth works, chimneys Nos. 1, 2, 5. Co. 1, 2, 5 and foundations for Failway lines elevation. (8.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. Co. 1, 2, 6 and 1			/			
One Dressing Plant:  (1.) Preliminary orushing building. (2.) Crushing building. (3.) Sorting hall. (4.) Ors, coke sah, and flue dust receiving bunkers. (5.) Transporter galleries with transloading points with partial machine equipment. (6.) Charge bunkers building. (7.) Half of the main ore dressing building (aglomerownia). (6.) Chimmey, roads etc.  Power Plants (1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (5.) Coal milding building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/6 EV with electrical equipment.  Steadlatorium and the main steelworks building - \$45,000 cu. meters, length about 190 m. (24) Tilting furnaces notes not clear whether open hearth or Bessamar - Spices pracelylnes. (5.) Hose, 1, 2, 5 and foundations for railway lines elevation. (6.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (tryperownia). (6.) Figurace repair workshop. (6.) Forge shop and furnace shop, assembly ef steel structures. (8.) Five chimneys of rolling-mill furnaces. (8.) Five onlimneys and lubrication sections, flux (wlewil), briquette and dolomite stores.  50X1-HU (Rollling Mills) (1.) Forge shop and furnace shop, assembly ef steel structures. (8.) Five chimneys of rolling-mill furnaces. (8.) Five chimneys of rolling-mill furnaces. (8.) Forge shop and furnace shop. (8.)		SECRET	CONTROL - U.S. OFFIC	TALS ONLY		
One Dressing Flant:  (1.) Preliminary orushing building. (2.) Crushing building. (3.) Sorting hall. (4.) Ore, coke sah, and flue dust receiving bunkers. (5.) Transporter galleries with transleading points with partial machine effilment. (6.) Charge bunkers building. (7.) Half of the main ore dressing building (aglomerownia). (6.) Chimmey, roads etc.  Power Plant; (1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (5.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Mater purifying plant. (6.) Main transformer station 110/6 KV with electrical equipment.  Stocklatorical and the main steelworks building - \$45,000 cu. meters, length about 190 m. (2.) Titting furnaces notes not clear whether open hearth or Bessenar - Spices precelyline". (5.) Hose, 1, 2, 5 and foundations for railway lines elevation. (6.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (tryperownia). (6.) Flee forced concrete foundations for railway lines elevation. (7.) Stripping plant (tryperownia). (6.) Reinforced concrete foundations for railway lines elevation. (7.) Stripping plant (tryperownia). (8.) Sleg and ladle preparation sections. (8.) Furnace repair workshop. (8.) Forge shop and furnace shop, assembly of steel structures. (8.) Five chimmeys of rolling-mill furnaces. (8.) Five chimmeys of rolling-mill furnaces. (8.) Roller latins shop. (8.) Replaced materials store. (9.) Furnace repair workshop. (1.) Forge shop and furnace shop, assembly of steel structures. (8.) Five chimmeys of rolling-mill furnaces. (8.) Five chimmeys of rolling-mill furnaces. (8.) Five chimmeys of rolling-mill furnaces. (8.) Forge shop and furnace shop, assembly of steel structures. (8.) Forge shop and furnace shop. (8.) Compressor station.	4 4		- 2 -	-		
One Dressing Flant:  (1.) Preliminary orushing building. (2.) Grushing building. (3.) Sorting hall. (4.) Ore, coke ash, and flue dust receiving bunkers. (5.) Transporter galleries with transleading points with partial machine equipment. (6.) Charge bunker building. (7.) Half of the main ore dressing building (aglomerownia). (8.) Chimmey, roads etc.  (8.) Chimmey, roads etc.  (8.) Chimmey, roads etc.  (8.) Coal milding of 235,500 cu. meters capacity is in a finished state. (8.) Coal milding building. (8.) Coal milding building. (8.) Main switching and distribution plant. (8.) Main switching and distribution plant. (8.) Main switching and distribution plant. (8.) Main transformer station 110/6 KV with electrical equipment.  Sitch Manufacture of the main steelworks building - 545,000 cu. meters, length about 190 m.  (24) Tilting furnaces notes not clear whether open hearth or Bessenar - Spices prescryiner). (8.) Nos. 1, 2, 5 and foundations of Ro. 6 Sarth works, chimneys Nos. 1, 2, 5 and foundations for railway lines elevation. (8.) Break forces concrete foundations for railway lines elevation. (8.) Repartic (sic) powdered materials store. (8.) Repartic (sic) powdered materials store. (8.) Furnace repair workshop. (8.) Fire chimneys of rolling-mill furnaces. (8.) Coaperses station.					50V4 I	
(1.) Preliminary crushing building. (2.) Crushing building. (3.) Sorting hall. (4.) Ore, coke sah, and flue dust receiving bunkers. (5.) Transporter galleries with transleading points with partial machine equipment. (6.) Charge bunker building. (7.) Half of the main ore dressing building (aglomerownia). (8.) Chimmey, roads etc.  Power Plants (1.) Main building of 255,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Cosl mulcoding bunkers. (4.) Cosl milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/ 6 KV with electrical equipment.  Sicolatory is a second part of steelworks building - \$45,000 cu. meters, length about (1.) Part I of the main steelworks building - \$45,000 cu. meters, length about (2.) Tilting furnaces  "piece pracehylms"). (3.) Hose 1, 2, 5 and foundations of No. 4 sarth works. (4.) Second part of steelworks building - sarth works, chimneys Hos. 1, 2, 5. (6.) Magnetic (sic) powdered materials store. (6.) Magnetic (sic) powdered materials store. (6.) Briting plant (stryperownia). (6.) Esting and ladde preparation sections, flux (wlewki), briquette and dolomite stores. (7.) Furnace repair workshop. (1.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller nounting shop. (4.) Roller mounting shop. (5.) Roller mounting shop. (6.) Pemple gration No. 6. (6.) Compressor station.				<u> </u>	50X1-I	HUN
Crushing bullding. So Sorting hall. So Ors, coke ash, and flue dust receiving bunkers. Cry, coke ash, and flue dust receiving bunkers. Cry, coke ash, and flue dust receiving bunkers. Charge bunker building. That of the main ore dressing building (aglomerownia). Chimmey, roads etc.  Power Plant;  (1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Coal unloading bunkers. (4.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Mater purifying plant. (8.) Main transformer station 110/6 KV with electrical equipment.  Siteal minutes.  10.) Part I of the main steelworks building - \$45,000 cu. meters, length about 190 m. (2.) Tilting furnaces plant. (3.) Second part of steelworks building - earth works, chimneys Hos. 1, 2, 3. (2.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (stryperownia). (8.) Hagnetic (sic) powdered materials store. (8.) Second part of steelworks building - earth works, chimneys Hos. 1, 2, 3. (3.) (8.) Eagle and ladle preparation sections, flux (wlewki), briquette and dolomite stores.  (9.) Sign and ladle preparation sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  Explication and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  Explication and lubrication sections, flux (wlewki), briquette and dolomite stores.  (2.) Five chimneys of rolling-mill furnaces. (3.) Reller nounting shop. (4.) Roller mounting shop. (5.) Furnacer repair workshop. (6.) Purposers station. (7.) Furnacer sub-station. (8.) Furnacer sub-station.	Ore	Dressing Plant	1	, ,	-	
2. Crushing building. 3. Sorting hall. 4. Ors, coke ash, and flue dust receiving bunkers. 5. Transporter galleries with transleading points with partial machine equipment. 6. Charge bunker building. 7. Half of the main ore dressing building (aglomerownia). 6. Chimney, roads etc.  Power Plant; 6. Chimney, roads etc.  Power Plant; 6. Main building of 255,500 cu. meters capacity is in a finished state. 2. Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. 3. Coal unloading bunkers. 5. Main switching and distribution plant. 6. Coal store elevation. 7. Water purifying plant. 6. Main transformer station 110/ 6 KV with electrical equipment.  Sitchimneys and the main steelworks building - \$45,000 cu. meters, length about 190 m.  2. Tilting furnaces plant (stryperownia). 6. Second part of steelworks building - earth works, chimneys Nos. 1, 2, 3. Sec. 1, 2, 3 and foundations for railway lines elevation. 6. Magnetic (sic) powdered materials store. 6. Magnetic (sic) powdered materials store. 7. Ever chimneys of rolling-mill furnaces, flux (wlewki), briquette and dolomite stores.  8. Roller nounting shop. 8. Roller nounting shop. 8. Roller nounting shop. 8. Powging station No. 4. 8. Compressor station.						
(3.) Sorting hall. (4.) Ore, coke sah, and flue dust receiving bunkers. (5.) Transporter galleries with transleading points with partial machine equipment. (5.) Charge bunker building. (7.) Half of the main ore dressing building (aglomerownia). (8.) Chimmey, roads etc.  Power Plant; (1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Coal unloading bunkers. (4.) Coal inling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/6 KV with electrical equipment.  Siteadurophism (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m. (24) Tilting furnaces (24) Tilting furnaces (24) Tilting furnaces (24) Tilting furnaces (25) Res. 1, 2, 3 and foundations of No. 4 Sarth warks. (5) Res. 1, 2, 5 and foundations for railway lines elevation. (6) Magnetic (sto) powdered naterials store. (7.) Bripping plant (stryperownia). (8.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. (6) Pirrace repair workshop. (9.) Sleg and ladle preparation sections. (10.) Furnace repair workshop. (11.) Ladle cleaning and lubrication sections, flux (wlewii), briquette and dolomite stores.  (10.) Forge shop and furnace shop, assembly of steel structures. (10.) Forge shop and furnace shop, assembly of steel structures. (10.) Furnace repair workshop. (10.) Roller nounting shop. (10.) Main with a steel workshop. (11.) Ladle cleaning and lubrication sections, flux (wlewii), briquette and dolomite stores.	(1.)					
(a.) Ore, coke such, and flue dust receiving bunkers.  (b.) Transportor galleries with transloading points with partial machine equipment.  (c.) Charge bunker building.  (7.) Haif of the main ore dressing building (aglomerownia).  (a.) Chimmey, roads etc.  Power Plant;  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal unloading bunkers.  (4.) Coal miling building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  Stread working with  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m.  (2.) Titting furnaces place of the steelworks building - earth works, chimmeys Nos. 1, 2, 5 m.  (5.) Reinforced concrete foundations of, No. 4 Warth works, chimmeys Nos. 1, 2, 5 m.  (6.) Hagnetic (sic) powdered naterials store.  (7.) Bripping plant (stryperownia).  (8.) Five chimmeys of rolling-mill furnaces.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimmeys of rolling-mill furnaces.  (3.) Roller normating shop.  (4.) Roller momenting shop.  (5.) Mechanical workshop.  (6.) Pamping station No. 5.  (6.) Transformer sub-station No. 5.  (6.) Transformer sub-station No. 5.  (6.) Compresser station.		Crushing building	ng.	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		
(5.) Transporter galleries with transleading points with partial machine edilipment.  (6.) Charge number building.  (7.) Half of the main ore dressing building (aglomerownia).  (8.) Chiarge number building.  (8.) Chiarge, roads etc.  Prower Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (8.) Coal milling building.  (8.) Main switching and distribution plant.  (8.) Main switching and distribution plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  Sixed works and formaces proceed the main steelworks building - 345,000 cu. meters, length about 190 m.  (2.4) Tilting furnaces proceed to the main steelworks building - and the works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys Nos. 1, 2, 5 meters of steelworks building - earth works, chimneys of steelworks building - earth works, chimneys of steelwo		Sorting Daile	and fine dust magel w	ina himbana		
(c.) Charge bunker building.  (7.) Haif of the main ore dressing building (aglomerownia).  (6.) Chimmey, roads etc.  Power Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal unloading bunkers.  (4.) Coal milling building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  Streakswires and the main steelworks building - 345,000 cu. meters, length about 190 m.  (2.) Tilting furnaces notes not clear whether open hearth or Bessemer - 50X1-HU  (3.) Hess. 1, 2, 5 and foundations of, No. 4 warth works, chimneys Nos. 1, 2, 5 and foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Bripping plant (stryperownia).  (9.) Slag and ladde preparation sections.  (6.) Furnace repair workshop.  (8.) Roller mounting shop.  (8.) Roller laths shop.  (8.) Powerses station.  (8.) Pemping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.					mertial machine	
(6.) Charge bunker building. (7.) Half of the main ore dressing building (aglomerownia). (8.) Chimmey, roads etc.  Power Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (8.) Coal unloading bunkers. (4.) Coal milling building. (6.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Mater puritying plant. (8.) Main transformer station 110/6 EV with electrical equipment.  Stochtmorks:  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m. (2.4) Tilting furnaces  "place preceivine"). (3.) Bes. 1, 2, 5 and foundations of No. 4 warth warks. (4.) Second part of steelworks building - sarsh works, chimneys Nos. 1, 2, 5. (6.) Magnetic (sio) powdered materials store. (6.) Magnetic (sio) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kafarownia). (9.) Slag and ladde preparation sections. (10.) Furnace repair workshop. (11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller nounting shop. (4.) Pamping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compresser station.	New A &		The second of th	Paris and	F-1. 1.1.1.	
(8.) Half of the main ore dressing building (aglomerownia).  (8.) Chimmey, roads etc.  Power Plant;  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal milding building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  Statistic furnaces notes not clear whether open hearth or Bessamer 50X1-HU  (1.) Part I of the main steelworks building - 845,000 cu. meters, length about 190 m.  (24) Tilting furnaces notes not clear whether open hearth or Bessamer 50X1-HU  (8.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5; Keinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Stripping plant (stryperownis).  (8.) -?- (kafarownia).  (9.) Slag and ladis preparation sections, flux (wlewil), briquette and dolomite stores.  (1.) Furnace repair workshop.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller nounting shop.  (4.) Roller mounting shop.  (5.) Mechanical workshop.  (6.) Pemping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.	(6.)		uilding.			
Power Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal unloading bunkers.  (4.) Coal milling building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  Stick(Minushamana)  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m.  (2.4) Tilting furnaces note: not clear whether open hearth or Bessemar - 7piece precedylner).  (5.) Ross 1, 2, 3 and foundations of No. 4 Sarth marks.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 3.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Estripping plant (stryperownia).  (6.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  (7.) Furnace repair workshop.  (1.) Porge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (5.) Roller nounting shops.  (5.) Roller nounting shops.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compressor station.		Half of the main	n ore dressing build:	ing (aglomerownia	s) <sub>10</sub>	
(1.) Main building of 235,500 cu. meters capacity is in a finished state. (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Coal wholeding bunkers. (4.) Coal wilding building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/ 6 KV with electrical equipment.  Sited Ambridge Aller.  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m. (244) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU (8.) Boss 1, 2, 3 and foundations of No. 4 Sarth marks. (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 3 and foundations for railway lines elevation. (6.) Magnetic (sio) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kefarownia). (9.) Slag and ladle preparation sections. (9.) Slag and ladle preparation sections, flux (wlewki), briquette and dolomite stores.  (2.) Furnace repair workshop. (1.) Porce shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller nounting shop. (4.) Roller nounting shop. (5.) Mechanical workshop. (6.) Pamping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.	(8.)	Chimney, roads			1	
Power Plant:  (1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal wholeding bunkers.  (4.) Coal milling building.  (5.) Main awitching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.   Standard plant of the main steelworks building - \$45,000 cu. meters, length about 190 m.  (24) Filting furnaces notes not clear whether open hearth or Bessemar - 50X1-HU  (8.) Boss 1, 2, 3 and foundations of No. 4 warth works, chimneys Nos. 1, 2, 3 and foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kefarownia).  (9.) Slag and ladle preparation sections.  (10.) Furnace repair workshop.  (11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller nounting shop.  (5.) Mechanical workshop.  (6.) Pemping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compressor station.			rs minus	le be read as a	知题50X1-HUM	
(1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal milading building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 180 m.  (2.) Filting furnaces notes: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Nos. 1, 2, 3 and foundations of No. 4 earth works.  (4.) Scond part of steelworks building - earth works, chimneys Nos. 1, 2, 3.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladie preparation sections.  (1.) Furnace repair workshop.  (1.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Five chimneys of rolling-mill furnaces.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller nounting shop.  (4.) Roller mounting shop.  (5.) Moshamical workshop.  (6.) Pemping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.			of the same of the same	•	00/(1/10//	
(1.) Main building of 235,500 cu. meters capacity is in a finished state.  (2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete.  (3.) Coal milading building.  (5.) Main switching and distribution plant.  (6.) Coal store elevation.  (7.) Water purifying plant.  (8.) Main transformer station 110/6 KV with electrical equipment.  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 180 m.  (2.) Filting furnaces notes: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Nos. 1, 2, 3 and foundations of No. 4 earth works.  (4.) Scond part of steelworks building - earth works, chimneys Nos. 1, 2, 3.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sio) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladie preparation sections.  (1.) Furnace repair workshop.  (1.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Five chimneys of rolling-mill furnaces.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller nounting shop.  (4.) Roller mounting shop.  (5.) Moshamical workshop.  (6.) Pemping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.	enter de la	A Thermal				
(2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Coal willoading bunkers. (4.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Mater purifying plant. (8.) Main transformer station 110/6 KV with electrical equipment.  50X1-HU  Street of the main steelworks building - \$45,000 cu. meters, length about 190 m. (2.) Tilting furnaces note: not clear whether open hearth or Bessemer - 50X1-HU  (8.) Wes. 1, 2, 3 and foundations of No. 4 warth works. (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. Reinforced concrete foundations for railway lines elevation. (5.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kafarownia). (9.) Slag and ladle preparation sections. (10.) Furnace repair workshop. (11.) Ladle cleaning and lubrication sections, flux (wiewi), briquette and dolomite stores.  (12.) Forge shop and furnace shop, assembly of steel structures. (13.) Roller laths shop. (4.) Roller laths shop. (5.) Repaing station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.	Powe	r Plant:				
(2.) Assembly of boilers No. 1 and No. 2, and turbo-generator No. 2 complete. (3.) Coal willoading bunkers. (4.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Mater purifying plant. (8.) Main transformer station 110/6 KV with electrical equipment.  50X1-HU  Street of the main steelworks building - \$45,000 cu. meters, length about 190 m. (2.) Tilting furnaces note: not clear whether open hearth or Bessemer - 50X1-HU  (8.) Wes. 1, 2, 3 and foundations of No. 4 warth works. (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. Reinforced concrete foundations for railway lines elevation. (5.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kafarownia). (9.) Slag and ladle preparation sections. (10.) Furnace repair workshop. (11.) Ladle cleaning and lubrication sections, flux (wiewi), briquette and dolomite stores.  (12.) Forge shop and furnace shop, assembly of steel structures. (13.) Roller laths shop. (4.) Roller laths shop. (5.) Repaing station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.	(1.)	Main building o	f 235.500 qu. meters	capacity is in	finished state-	
(3.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/ 5 KV with electrical equipment.  50X1-HU  Steal works  (1.) Part I of the main steelworks building - 545,000 cu. meters, length about 190 m. (2.) Tilting furnaces note: not clear whether open hearth or Bessemer - mpiece prischylne"). (3.) Mos. 1, 2, 5 and foundations of No. 4 Carth works, chimneys Nos. 1, 2, 5. (6.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. (6.) Hagnetic (sio) powdered materials store. (6.) Magnetic (sio) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kafarownia). (9.) Siag and ladle preparation sections. (10.) Furnace repair workshop. (11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (12.) Forge shop and furnace shop, assembly of steel structures. (13.) Roller laths shop. (4.) Roller laths shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.	(2.5					
(4.) Coal milling building. (5.) Main switching and distribution plant. (6.) Coal store elevation. (7.) Water purifying plant. (8.) Main transformer station 110/6 EV with electrical equipment.  50X1-HU  Stick (Mainthian and State of the main steel works building - \$45,000 cu. meters, length about 180 m. (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Nes. 1, 2, 5 and foundations of No. 4 carth works. (4.) Second part of steel works building - earth works, chimneys Nos. 1, 2, 5. (6.) Reinforced concrete foundations for railway lines elevation. (8.) Manetic (sic) pordered materials store. (7.) Stripping plant (stryperownia). (8.) -?- (kafarownia). (9.) Siag and laddle preparation sections. (10.) Furnace repair workshop. (11.) Forge shop and furnace shop, assembly ef steel structures. (12.) Five chimneys of rolling-mill furnaces. (3.) Roller laths shop. (4.) Roller laths shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.					•	
(6.) Coal store elevation.  (7.) Water purifying plant. (8.) Main transformer station 110/6 KV with electrical equipment.  50X1-HU  Stick(wireket ***********************************				•		
(7.) Water purifying plant. (8.) Main transformer station 110/6 EV with electrical equipment.  50X1-HU  Sich (works)  (1.) Part I of the main steelworks building - \$45,000 cu. meters, length about 180 m. (2.) Tilting furnaces notes not clear whether open hearth or Bessemar - 50X1-HU  (3.) Nos. 1, 2, 5 and foundations of No. 4 Carth works, chimneys Nos. 1, 2, 5. (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. (5.) Reinforced concrete foundations for railway lines elevation. (6.) Magnetic (sic) powdered materials store. (7.) Stripping plant (stryperownia). (8.) -? (kafarownia). (9.) Slag and ladle preparation sections. (9.) Furnace repair workshop. (1.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller lathe shop. (4.) Roller mounting shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (6.) Compressor station.	(5.)	Main switching	and distribution plan	1t.		
(8.) Main transformer station 110/6 KV with electrical equipment.  50X1-HU  Sich(Muniphase Main.)  (1.) Part I of the main steelworks building - 345,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Ness 1, 2, 5 and foundations of No. 4 earth works.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5. (6.) Reinforced concrete foundations for railway lines elevation.  (5.) Estinpoing plant (stryperownia).  (6.) Agnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  (10.) Furnace repair workshop.  (11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (12.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller mounting shop.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (6.) Compresser station.						
Stockdworker.  (1.) Part I of the main steelworks building - \$45,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Ness 1, 2, 5 and foundations of No. 4 Carth works.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 3.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  10.) Furnace repair workshop.  11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller nounting shop.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (6.) Compressor station.						
(1.) Part I of the main steelworks building - \$45,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Wese 1, 2, 3 and foundations of No. 4 earth works.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  (9.) Slag and ladle preparation sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Roller lathe shop.  (2.) Roller lathe shop.  (3.) Roller nounting shop.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (6.) Compressor station.	(8.)	Main transforme	r station 110/6 KV v	with electrical e	quipment.	
(1.) Part I of the main steelworks building - \$45,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Hese 1, 2, 5 and foundations of Ho. 4 earth works.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  Furnace repair workshop.  11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller mounting shop.  (5.) Mechanical workshop.  (6.) Pamping station No. 4.  (7.) Transformer sub-station No. 5.  (6.) Compressor station.		**	,		<b>50)</b> (4	
(1.) Part I of the main steelworks building - \$45,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Hos. 1, 2, 5 and foundations of No. 4 Carth works, chimneys Nos. 1, 2, 5.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -?- (kafarownia).  (9.) Slag and ladle preparation sections.  10.) Furnace repair workshop.  11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller nounting shop.  (5.) Machamical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (6.) Compresser station.					50X1	-HU
(1.) Part I of the main steelworks building - 545,000 cu. meters, length about 190 m.  (2.) Tilting furnaces note: not clear whether open hearth or Bessemar - 50X1-HU  (3.) Nos. 1, 2, 5 and foundations of No. 4 earth works, chimneys Nos. 1, 2, 5.  (4.) Second part of steelworks building - earth works, chimneys Nos. 1, 2, 5.  (5.) Reinforced concrete foundations for railway lines elevation.  (6.) Magnetic (sic) powdered materials store.  (7.) Stripping plant (stryperownia).  (8.) -! (kafarownia).  (9.) Slag and ladle preparation sections.  10.) Furnace repair workshop.  11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (5.) Roller lathe shop.  (4.) Roller nounting shop.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.	2. 2.	P. 19 man	•			
11.) Ladle cleaning and lubrication sections, flux (wlewki), briquette and dolomite stores.  50X1-HU  Rolling Mills  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller mounting shop.  (5.) Mechanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compressor station.	(4.) (5.) (6.) (7.) (8.) (9.)	Second part of Reinforced conc Magnetic (sic) Stripping plant -!- (kafarownia Slag and ladle)	steelworks building - rete foundations for powdered materials st (stryperownia). ). preparation sections.	- earth works, ch railway lines el bore.		<b>5•</b> ( )
dolomite stores.  [Rolling Mills				ions, flux (wlew)	i). briquette and	
Rolling Mills:  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller nounting shop.  (5.) Machanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.					1	
Rolling Mills  (1.) Forge shop and furnace shop, assembly of steel structures.  (2.) Five chimneys of rolling-mill furnaces.  (3.) Roller lathe shop.  (4.) Roller nounting shop.  (5.) Machanical workshop.  (6.) Pumping station No. 4.  (7.) Transformer sub-station No. 5.  (8.) Compresser station.			,	•	1	
(1.) Forge shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller lathe shop. (4.) Roller mounting shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.					50X1-	HU
(1.) Forge shop and furnace shop, assembly of steel structures. (2.) Five chimneys of rolling-mill furnaces. (3.) Roller lathe shop. (4.) Roller mounting shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.		- AW			•	
<ul> <li>(2.) Five chimneys of rolling-mill furnaces.</li> <li>(3.) Roller lathe shop.</li> <li>(4.) Roller mounting shop.</li> <li>(5.) Machanical workshop.</li> <li>(6.) Pumping station No. 4.</li> <li>(7.) Transformer sub-station No. 5.</li> <li>(8.) Compressor station.</li> </ul>	Roll	ing Mills				
<ul> <li>(2.) Five chimneys of rolling-mill furnaces.</li> <li>(3.) Roller lathe shop.</li> <li>(4.) Roller mounting shop.</li> <li>(5.) Machanical workshop.</li> <li>(6.) Pumping station No. 4.</li> <li>(7.) Transformer sub-station No. 5.</li> <li>(8.) Compressor station.</li> </ul>	/= 1	Towns above and			<b></b>	
(5.) Roller lathe shop. (4.) Roller mounting shop. (5.) Mechanical workshop. (6.) Fumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.					eures.	
(4.) Roller mounting shop. (5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub≃station No. 5. (8.) Compressor station.	\ <b>*</b> *\			905.		
(5.) Mechanical workshop. (6.) Pumping station No. 4. (7.) Transformer sub-station No. 5. (8.) Compressor station.						
(6.) Pumping station No. 4. (7.) Transformer sub⇔station No. 5. (8.) Compressor station.						
(7.) Transformer sub⇔station No. 5. (8.) Compressor station.						
(8.) Compressor station.						
				)		
	·-•/			•	50X1-HUM	
					3377110111	
	. (314)	Cara No and Cara				
Power Bumply Shops	Powe	r Bumply Shop	<b>B</b> _::			
	,					
(1.) Pumping station No. 1 and 3.						
(2.) Buildings containing waterworks, gasworks and telephone exchange department	3			smores end gereby	one excuange depar-	JE OT
(5.) Machinery for blast furnace.	>20					

	. /	7 · · · · · · · · · · · · · · · · · · ·	•		5
	SECRET/CONTRO	L - U.S. OFFI	CIALS ONLY	10.00	50X <sup>2</sup>
		- 8 -		4.	
(9.) Cable t (10.) Twenty	unnels with cal	oles. spetions, lo	r+vobtage powe;	supply.	50X1-H